

## Rank 1 Crosswalk Curb

Note the curb has no slope or textured area.



## Rank 2 Curb

Note that while the curb slopes onto the street, it does not have the yellow textured area.



## Rank 3 Crosswalk Curb

Note the slope onto the asphalt and yellow textured area to provide better traction.





# Alley Crossing

Note that neither side is up to ADA standards.





## Special Case

While the crossings in this photo do have the ADA ramps, they lead directly to a stormwater drain and render the ramps useless.





# Driveway Apron

Note the driveway apron does not slope smoothly out to the street.

